3 B 6

DATE: _____May, 1970

BRITISH LEYLAND MOTORS INC. 600 Willow Tree Road • Leonia • New Jersey 07605

SUBJECT:

MODELS:

Horn Maintenance

All Models

Under normal conditions, the Factory setting should not require attention but in the event of the horn failing, the current feed to horn terminals should be checked to ensure continuity.

Maintenance is restricted to keeping the terminals and surrounding areas clean only.

Under \underline{no} circumstances should the adjustment screw at the back of the horn be altered.