



DATE: May, 1970

BRITISH LEYLAND MOTORS INC.
600 Willow Tree Road • Leonia • New Jersey 07605

SUBJECT:

Front Seats

MODELS:

Austin America

Rattles from front seat frames may be caused by loose leg pivot pins.

Rectify as follows:-

- (1) Examine pins 'A' in frame tube.
- (2) If loose, remove seat cushion cover and foam pad.
- (3) Arc weld round end of pivot pin as shown attaching pin to tube.
- (4) Clean off and touch in with black paint.
- (5) Replace foam pad and cushion cover.

