TECHN	ICAL SERVICE BULLETIN
BRITISH	
	AUSTIN MG

NO	71-A-	11
110.		_

July 1971

MODELS:

Choke Cable Failure

Austin America

Investigation into the high incidence of failure of Austin America choke cables indicates that the majority of claims for this component are due to bent inner cable/knob shafts and not the result of a manufacturing defect.

In view of this, all dealers are requested to automatically return all displaced choke cables to your Distributor with the claim to confirm a manufacturing defect.

Any cables received with damaged or bent knob/shafts will be subject to automatic rejection.

SUBJECT: