

TECHNICAL SERVICE BULLETIN

NO. 71 B 11



September 1971

SUBJECT:

Lucas Alternators

MODELS:

Austin America (Air Conditioned)

Your attention is drawn to the fact that the model 17 ACR alternator as fitted to the air conditioned version of the Austin America should not be replaced in service by the model 16 ACR offered on the exchange program.

The reduced output of the 16 ACR unit compared with the 17 ACR would seriously affect the charging circuit efficiency.

Until such time as a similar exchange program is available on the 17 ACR unit replacement must be made using new alternators from stock.