

TECHNICAL SERVICE BULLETIN

73-D-5

NO.



Austin MG

July, 1973

SUBJECT:

AUTOMATIC TRANSMISSION

MODELS:

MARINA

Cases have been reported of complete failure of the automatic transmission, which has come about as a result of maladjustment of the selector linkage.

Please insure that the linkage is checked for proper adjustment at pre-delivery and subsequent servicing intervals. Details regarding the correct procedure are contained in the Marina workshop manual, section 44, page 44-30-04.

J.P.