

## TECHNICAL SERVICE BULLETIN

NO. 2 A 29

**AUSTIN MG**  
DIVISION

DATE: February 1, 1969

**BRITISH LEYLAND MOTORS INC.**  
600 Willow Tree Road • Leonia • New Jersey 07605

## SUBJECT:

GEARBOX

## MODELS:

AUSTIN HEALEY SPRITE - MK IV  
MG MIDGET - MK III

Difficulty in pulling up the gearbox to the engine may be due to the case assembly fouling the top left hand of the oil pump cover.

In such cases clearance should be given by removing a small amount of material from the inside of the casing where indicated by an arrow in the sketch.

