

Confidential

TECHNICAL SERVICE BULLETIN

NO.

2 A 30



DATE: February 1, 1969

BRITISH LEYLAND MOTORS INC.
600 Willow Tree Road • Leonia • New Jersey 07605

SUBJECT:

FAN BLADES FOULING AIR PUMP
PULLEY RETAINING BOLTS

MODELS:

AUSTIN AMERICA

A 5/32 in. thick packing piece, Part No. 12A 312, is now being fitted between the fan and water pump pulley.

This has necessitated lengthening the retaining bolts by 1/8 in. and their Part No. becomes HZS 0409. Vehicle change points are not available.

If a fan blade fouling condition occurs in service, Dealers may submit a warranty claim for replacing the fan and fitting the above packing piece.