
0	Confidential TECHNICAL SERVICE BU BRITISH AUSTIN	DIVISION RS INC.	NO. 2 A 35 NO. May 18, 1969	and a state of the
SUBJECT:	Engine Steady Bar	MODELS:	Austin America Automatic	100 - 001

Isolated cases have been reported of the engine steady bar to cylinder block securing bolt working loose and in extreme cases eventually breaking.



Would you please advise all service personnel to check and tighten this bolt if necessary during routine maintenance services.