Confidential TECHNICAL SERVICE BULI BRITISH LEYLAND BRITISH LEYLAND MOTORS 600 Willow Tree Road • Leonia • New Jerse	F 77 DATE: 2/1/70
SUBJECT:	MODELS:
CRANKSHAFT PRIMARY GEAR OIL LEAKAGE	ALL "A" SERIES ENGINES EQUIPPED WITH MANUAL TRANSMISSION

When attempting to cure complaints of oil leakage from the primary gear area, ensure the annular groove between the bushes in the bore of the primary gear is filled with one of the following greases or grease of like quality:

> Duckhams DB 500 Shell Retinex DX Castrol BNS