

Confidential

# TECHNICAL SERVICE BULLETIN

NO.

3 A 4



DATE: 3/1/70

**BRITISH LEYLAND MOTORS INC.**  
600 Willow Tree Road • Leonia • New Jersey 07605

SUBJECT:

Radiator Surround Rubber

MODELS:

Austin America

From Serial Number 104 (not equipped with evaporative loss control) and Serial Number 1931 equipped with evaporative loss control, the fitment of the radiator surround rubber was discontinued.

As this assists engine cooling, attempts to close the gap which now exists between the radiator and cowl should not be made.