

Confidential
TECHNICAL SERVICE BULLETIN

NO. 3 A 7



DATE: May, 1970

BRITISH LEYLAND MOTORS INC.
600 Willow Tree Road • Leonia • New Jersey 07605

SUBJECT:

MODELS:

Cooling System Expansion

Austin America

In the event of expansion tank fitting lug breakage, the tank can be refitted using a support strap as illustrated below.

These can be made locally from 16 gauge mild steel to the dimensions shown or ordered under part number ACA 1791 strap 1 of, and 31G 1181 mounting plate 2 of.

The mounting plates must be fitted between the tank and the body brackets with curved edges directed towards the tank.

