

Confidential

TECHNICAL SERVICE BULLETIN

NO.

3 D 8



DATE: May, 1970

BRITISH LEYLAND MOTORS INC.
600 Willow Tree Road • Leonia • New Jersey 07605

SUBJECT:

MODELS:

3rd to 4th Speed Synchromesh Hub

Austin America

Isolated cases have been reported of difficulty being experienced in the fitting of replacement synchronizer assembly, part number 22G 1110, to the existing 3rd motion shaft.

In this event the replacement assembly should be located on all positions on the shaft in an effort to locate a free-fitting spline or alternatively, carry out selective fitting of this part, from various samples from stock.

It is essential that the hub is a free fit on the 3rd motion shaft before reassembling.