

TECHNICAL SERVICE BULLETIN



AUSTIN MG
DIVISION

3 F 7

NO.

October, 1970

SUBJECT:

Wire Wheels

MODELS:

MG Midget
MGB
MGB-GT

Recently we have been receiving warranty claims relating to difficulties experienced in removing wire wheels from hubs on MG cars.

Although no routine maintenance is mentioned in the "Passport to Service" it is strongly recommended that the wheels are removed periodically, the splines greased and the spokes checked for tightness.

As of this date we will not accept any further claims for wire wheel and/or hub replacement as the result of seized or rusted wheels to hub splines.