

# TECHNICAL SERVICE BULLETIN

NO. 71-A-12



July 1971

SUBJECT:

Gulp Valves

MODELS:

All Models

Please refer to Service Bulletins numbered 2-A-43 dated November 1, 1969 and 3-A-9 dated September 24, 1970 intended to encourage proper diagnosis of emission equipment and prevent unnecessary gulp valve replacement at owner or warranty expense.

As the result of continued and unnecessary warranty expense the manufacturer has purchased a testing machine which categorically determines the validity of "defective" units and a recent exercise conducted by Nisonger Corporation and supervised by British Leyland Motors Inc. confirmed that from 100 suspect valves tested 60 proved satisfactory.

Therefore, effective immediately any gulp valves which are returned to Nisonger Corporation and checked as satisfactory will be returned to you via your Distributor and the claim debited.