

# TECHNICAL SERVICE BULLETIN

NO. 71 B 10



June, 1971

SUBJECT:

Battery Equipment

MODELS:

MGB

Batteries on cars in service when used in pairs as they are on the MGB, should not generally be replaced individually.

All charging systems operate on the system of supplying current in proportion to the internal resistance of a battery. Therefore, if batteries are replaced individually in an MGB and one battery is in poorer condition than the other a failure can be expected. This generally means that the battery in better condition receives an excess charge and subsequently fails.