

TECHNICAL SERVICE BULLETIN

71 B 7

NO.



January, 1971

SUBJECT:

Ignition Locks

MODELS:

MGB
MG Midget

On the latest production cars the "I" position on the ignition lock is an accessory position in which the heater, wipers, etc. will operate but the ignition will not.

Due to revised construction the buzzer will continue to sound after the key is removed until the steering wheel is turned to allow the lock bolt to drop into the column.