

TECHNICAL SERVICE BULLETIN

NO. 72 A 2



April, 1972

SUBJECT:

H.I.F. Carburetor

MODELS:

MGB

Extreme care must be exercised when using high pressure air lines to clean the fuel intake pipes on the H.I.F. carburetor.

Cases have been reported where the floats have sustained damage as a result of this method of cleaning being utilized.