

# TECHNICAL SERVICE BULLETIN

NO. 73-A-3



# Austin MG

March, 1973

SUBJECT:

CARBURETORS

MODELS:

ALL MODELS

Recent inspections of carburetors returned under warranty indicate that replacements have been made unnecessarily; therefore, effective immediately, any carburetor unit changes must be subject to prior authorization from the distributor. All units changed are subject to testing and will be returned with reversal of the related claim unless a clearly discernable defect exists and is accurately described.

In the event that carburetion problems are suspected, the assistance of the distributor service representative should be obtained.

J.P.