

TECHNICAL SERVICE BULLETIN

NO. 73-A-5



March, 1973


SUBJECT:

THROTTLE CABLE

MODELS:

MGB & MGB/GT

When replacing carburetors on these models, insure that the free end (A) of the throttle cable below the throttle cable trunion (B) cannot interfere with the free operation of the throttle; it is essential that it be routed on the engine side of the choke lever spindle (C).



SB-A 2/21/73