

# TECHNICAL SERVICE BULLETIN

NO.

73-D-3



# Austin MG

March, 1973

SUBJECT:

BORG WARNER AUTOMATIC TRANSMISSION  
FLUID LEVEL CHECK

MODELS:

MARINA

Due to fluid splash and frothing in the dipstick tube on Borg Warner automatic transmission units, it is very often difficult to obtain consistent fluid level readings.

As a result of this, a new fluid level checking procedure is recommended as follows:

Run the vehicle at least five miles or until the transmission unit has reached its normal operating temperature; then, park the vehicle on level ground, apply the handbrake, and move the selector lever to "P" (Park). Switch off the engine; and, within half a minute, check the fluid level with the engine switched off.

PB-D 2/28/73