

TECHNICAL SERVICE BULLETIN

73-D-4A

NO.



Austin MG

SUBJECT:

GEARBOX (MANUAL) DRAIN PLUG

MODELS:

AUSTIN MARINA

Technical Service Bulletin 73-D-4 advised the deletion of the gearbox drain plug on all Austin Marinas. Please disregard this information inasmuch as the drain plug has been reinstated in order to facilitate machining operations. It is not, however, considered necessary to replace the oil at servicing intervals; and the gearbox will require topping up only.

Issue 54/595