

TECHNICAL SERVICE BULLETIN

NO. 73-E-1



Austin MG

NOVEMBER, 1973

SUBJECT:

PAINT SPOTTING

MODELS:

ALL MODELS

There have been recent instances of apparent paint defects reported on the horizontal surfaces of cars both when early in service and sometimes after a period of use. The defect appears similar to liquid droplets or spots on various parts of the surfaces but is mainly limited to the horizontal surfaces.

Investigations indicate that this condition is the result of atmospheric pollutants and, therefore, refinishing of vehicles for the removal of this condition is not a matter for warranty coverage.

Certain types of wax have been known to aggravate this condition and sometimes wax removal and cleaning with a good liquid polish will restore the finish to an acceptable condition.

R.W.T.