



SERVICE

TECHNICAL SERVICE BULLETIN

The British Motor Corporation / Hambro Inc.

734 GRAND AVENUE, RIDGEFIELD, NEW JERSEY 07657

January 30, 1967

TO ALL DISTRIBUTORS AND DEALERS

Re: Radiator Recoring

Cooper "S"

If radiators fitted to the above vehicle are sent to specialists for re-coring, it is of the utmost importance they are informed the core has 16 Gills per inch and not 13 as fitted in a standard 850.