



TECHNICAL SERVICE BULLETIN

British Motor Holdings (U.S.A.) Inc.

734 GRAND AVENUE, RIDGEFIELD, NEW JERSEY 07657

April 1, 1968

TO ALL DISTRIBUTORS AND DEALERS

Re: Exhaust Emission Air Pump
Lucas Part Number 54730544

1968 MGB and MGB/GT
Austin Healey Sprite Mk IV
MG Midget Mk III
Austin America

It will be noted the exhaust emission air pump fitted to all the above 1968 models is manufactured by Lucas Electrical Services and carries the replacement Part Number as quoted above.

If, at any time, a fault is indicated with an air pump, it should be replaced as a unit using the normal Warranty procedure for proprietary equipment and not repaired as detailed in the B.M.C. Emission Manual, AKD 4957. The pulley and four mounting bolts should be removed from the old pump and fitted to the replacement unit.