

Confidential

# TECHNICAL SERVICE BULLETIN

NO.

2 A 28



DATE: February 1, 1969

**BRITISH LEYLAND MOTORS INC.**  
600 Willow Tree Road • Leonia • New Jersey 07605

**SUBJECT:**

Crankshaft Primary/Output  
Gear Thrust Washer

**MODELS:**

Austin America

The correct part numbers for the selective converter output gear thrust washers as fitted to the Automatic America are: 22A 546, 22A 547, 22A 548, 22A 549; NOT 22A 321, etc.

You will note these are the same as fitted to the America stick shift primary gear.