



TECHNICAL SERVICE BULLETIN

The British Motor Corporation / Hambro Inc.
734 GRAND AVENUE, RIDGEFIELD, NEW JERSEY 07657

September 29, 1967

TO ALL DISTRIBUTORS AND DEALERS

Re: Brake Disc Re-Grinding

All Models

The practice of re-grinding or skimming of brake discs in an attempt to remove scoring or grooving by brake pads must be discontinued.

Any reference to this procedure in Workshop Manuals must be ignored.