

Confidential

TECHNICAL SERVICE BULLETIN

NO. 3 D 1



DATE: 1/15/70

BRITISH LEYLAND MOTORS INC.
600 Willow Tree Road • Leonia • New Jersey 07605

SUBJECT: REAR AXLE OIL LEAKS	MODELS: MGB/MGC
-------------------------------------	------------------------

A pinion oil seal using rubber of an improved material was introduced at the following change points:

<u>Model</u>	<u>Chassis No.</u>
MGB	141148
MGB/GT	158239
MGC	4691

Old seal number BTC 348 was changed to 88G490 and this later seal only should be used for service.