

TECHNICAL SERVICE BULLETIN

NO. 71 F 15



July, 1971

SUBJECT:

Inertia Valve
Recall Campaign #A126

MODELS:

Austin America

1971 Austin Americas with serial numbers higher than AA2SDUB-5671 M have been modified in production and should not be included in Recall #A126.