0	Confidential TECHNICAL SERVICE I BRITISH AUSTIN LEYLAND BRITISH LEYLAND MO 600 Willow Tree Road • Leonia • New	DIVISION	DATE:	NO. 2 A 40 July 1, 1969
SUBJECT:		MODELS:		
	Cylinder Head Gasket		Austin America	

To obliviate cylinder head gasket leakage a modified head gasket part number 12G 2230 was introduced at engine number 12H 2G1B-H-1216 (Manual) and 12H 232B-H-4857 (Automatic). This gasket is interchangeable with the early type and should be installed whenever the cylinder head is removed for any reason.