

NO. 2 A 42

10/15/69 DATE: _____

BRITISH LEYLAND MOTORS INC. 600 Willow Tree Road • Leonia • New Jersey 07605

SUBJECT:

Replacement Water Pump Part Number 12H 1503 R MODELS:

MGB

It has recently been brought to our attention that the hub of replacement water pumps is a smaller diameter than the original, therefore the original water pump pulley is a loose fit on the replacement pump.

All dealers are requested to fit both hub and pulley from original water pump to the replacement pump, when fitting MGB pumps, Part Number 12H 1503 R.