



TECHNICAL SERVICE BULLETIN

The British Motor Corporation / Hambro Inc.

734 GRAND AVENUE, RIDGEFIELD, NEW JERSEY 07657

January 30, 1967

TO ALL DISTRIBUTORS AND DEALERS

Re: Oil Pressure Gauge Needle
Flutter

Austin Healey Sprite
MG Midget
MGB

This can be overcome by the fitting of a damping plug,
Part No. 27H 7877, to the pressure gauge.

This plug is easily pressed into the orifice of the union
on the gauge, which need not be removed from the car for
this purpose.