

TECHNICAL SERVICE BULLETIN

Confidential

British Motor Holdings (U.S.A.) Inc. 734 GRAND AVENUE, RIDGEFIELD, NEW JERSEY 07657


October 16, 1968

NO. 2 B 23

Re: Bulb Replacement Brake Pressure Check Light Switch

All 1968 Models

To replace or tighten the bulb in the Brake Pressure Check Switch, remove the switch assembly from the facia panel, Austin America and early sports cars by depressing the four lugs on the outside of the switch casing. Gently press the switch rocker pivot lugs inwards and withdraw the rocker with lens from the casing.



NOTE On the later 1968 Sports Cars the above switch is held into the facia panel by a wire clip. Push the clip in direction of the arrow to remove the switch.

Push spring clip in this direction.

MG • AUSTIN HEALEY • MORRIS • AUSTIN • SPRITE • MIDGET