

Confidential

TECHNICAL SERVICE BULLETIN

NO.

2 B 24



DATE: February 1, 1969

BRITISH LEYLAND MOTORS INC.
600 Willow Tree Road • Leonia • New Jersey 07605


SUBJECT:

Radio Interference From
Wiper Motor

MODELS:

All Models with Two Speed
Wiper Motors

Complaints of radio interference from the wiper motor can be eliminated by the addition of a heavy ground wire (braided type is most suitable) from one of the wheel box cover screws to a good ground point.



Braided ground
wire on Austin
America installation.