

Confidential

TECHNICAL SERVICE BULLETIN

2 B 29

NO.



DATE: July 1, 1969

BRITISH LEYLAND MOTORS INC.
600 Willow Tree Road • Leonia • New Jersey 07605

SUBJECT:

Bonnet Safety Catch
Fouling Wiring Harness

MODELS:

MGC

At serial number 4567 a harness protector plate was introduced to prevent the bonnet safety catch from fouling the wiring harness.

Vehicles prior to the above serial number should be examined and the harness re-routed as necessary to correct this condition.